



4296 York Road
 New Oxford, Pa 17350
 717.624.2900 F-717.624.7661
www.golfcartservices.com

Electric Golf Cars

Reconditioning Style

<u>Silver</u>	<u>Gold</u>		
\$1,800	\$2,100	2005 E-Z-GO PDS	Green
\$2,000	\$2,300	2006 E-Z-GO PDS	Green/White
\$2,000	\$2,300	2007 TXT/E w/soc	Green

NEW 2010 E-Z-GO RXV/E Freedoms starting at \$5999

NEW 2010 E-Z-GO TXT/48V at \$4900

Ask about cars that are ready in our showroom and outside sales area!

Silver Reconditioning: 30 day warranty on the major drive train.

Gold Reconditioning: 60 day warranty; all parts & labor; In-house.

Above prices do not include options (tops, windshields, etc.)

See the Optional Equipment listing page for options/accessories

Car pricing and availability subject to change

Silver Reconditioning: We load test your batteries with a state of the art computerized discharge tester making sure they discharge at 80 minutes, or better of run time. This is the equivalent of playing two rounds of 18 holes of golf. Battery charger is checked and working correctly. Seat covers will be used but in good condition with no rips/holes. Car is checked to ensure it starts, brakes, and steers correctly. Car is cleaned with a power wash.

30 day warranty on the major drive train (batteries-motor-charger) performed in-house at GCS.

Transportation to/from GCS is not included in the warranty coverage.

Gold Reconditioning: We load test your batteries with a state of the art computerized discharge tester making sure they discharge at a level of 80 minutes, or better, of run time. We replace the battery wires and solenoid with new. Battery charger is checked and working correctly. Pull rear drums, inspect brakes and replace pads, if worn. Grease all fittings. Remove course logos and decals. Automatically replace both seat covers with new. Check over entire cart to ensure your car starts, brakes, and steers correctly. Car is power washed and detailed.

60 day warranty on the entire car covering all parts and labor performed in- house at GCS.

Transportation to/from GCS is not included in the warranty coverage.